Approved For Release 2003/01/24: CIA-RDP62B00844R000200260138-3

SAPC-2681 Copy 2 of 7

MEMCHANDIM FOR THE RECORD

25 November 1955

SUBJECT : Preliminary Comments on Operational Deficiencies Report

MEMORRACE: Memorandum to Project Director from Commander, SAC Lisison Unit dated 16 November 1955 - Three Attachments: Report #1 - Supervisory Visit Report. Report #2 - Memorandum Highlighting Problems which will effect the flying training program. Report #3 -

Organizational charts.

The following are extremely preliminary comments on the referenced reports. Except as noted, these comments are addressed specifically to the numbered paragraphs in Report #2, which appear to cover all the major recommendations.

25X1A

1. Paragraph 1 of Report #2: It is agreed that the Base Operations at should include a Base Flight Section. We are already planning to sapply two men who will be primarily responsible for the C-47 and the L-20.

An effort will be made to secure from one or two civilian 25X1A truck drivers to move fuel trucks around the flight lines. These may later be replaced with Air Force personnel as recommended in paragraph III of Report #2. It is our view that the SAC Liaison Unit should provide two men to form part of the Base Flight Section for maintenance and servicing of the T-33's.

2. Paragraph 2 of Report #2: We agree that the T/O of Detachment A (and subsequent detachments) should be expanded to provide for individuals to mintain specialized ground power equipment, especially the MA-2's. Our present plan is to secure two mechanics for this purpose from Lockheed and for them at once to be put through factory training on the WA-2 then assigned to Detachment A Our feeling is that in view of the rather liberal allowance for maintenance personnel for the primary mission aircraft, the two specialists on ground power equipment will be able to draw on aircraft maintenance personnel to handle the job. This estimate of requirements is of course subject to revision in the light of experience.

25X1A

25X1A

3. Faragraph 3 of Report #2: We agree that there is insufficient
PCL storage and the personnel required to move PCL trucks. We
will take steps immediately to obtain one additional 5,000 gallon trailer per
type of fuel. We will arrange with to provide drivers pending reprotection of Air Force personnel (see paragraph 1 above.)

25X1A

25X1A

4. Paragraph 4 of Report #2: We are very reluctant to see T-28's stationed partly because of the special maintenance problems this will involve and partly because the whole scale of the operation there is expanding so rapidly. We would like to have views on the feasibility of using the L-20 for chase purposes at take-off and landings.

25X1A

-9-

If it is feasible, and if necessary we could have another L-20 assigned to the Base which would involve less additional maintenance than two T-28's.

	THE RESE AUTER ADDITE THAT THE TEST CONTINUES INTRACTIONS AND AND ADDITED AND ADDITED AND ADDITED ADDITED AND ADDITED ADDITED AND ADDITED ADDITED AND ADDITED ADDITED ADDITED AND ADDITED ADDITED ADDITED ADDITED AND ADDITED ADDI
	5. Paragraph 5 of Report #2: Already taken care of.
25X1A	6. Paragraph 6 of Report #2: The only comment we can make on 25X1A recommendation is to say that we are endorsing it and passing it to see and Agency personnel officers. We are acutely aware of the deficiencies to which he refers.
25X1A	7. Paragraph 7 of Report #2: We agree that we should take advantage of the warehouse approaching completion to establish a Base Supply Section which will support all aircraft and other equipment that is essigned to Detachment A and later Detachments. It is also clear that some additional personnel will be needed to manage the Base Supply Section.  Tentative opionion, however, is that we should move with the greatest possible speed to obtain some additional personnel but to assign them to Detachment A and to expand the T/O for Detachment A to allow for a larger Supply Section eversees as well as On this conception, the functions of the Supply Section will be handled by two or three permanent Base personnel with the help of an expanded Supply Section in each successive
25X1A	Betachment.
25X1A	8. Paragraph 7 of Report #1: We agree that there should be a second 0-11-A crash fire truck and that the complement of fire fighting personnel there should be sufficient to man both trucks, though it need not be the equivalent of two complete crash crews. Something like 12 men on duty at the Base at all times might be sufficient. This would require at least 18 assigned to allow for rotation. We will proceed forthwith to obtain the second fire truck and to requisition for additional personnel.  25X1A
25X1A	9. Organization charts - Report #3: Chart #1 covering the organization of the whole project is in full accord with our understanding of the relationships that have been established. With reference to Chart #2 of the organization, we are in agreement as indicated above on the need for the two additional sections indicated in red. For the present, however, we plan to continue the arrangement whereby personnel and administration, material, and security are all grouped together in a single support division. If the material problem grows in scope, we may decide at a subsequent time to establish a separate material division at the Base corresponding to the arrangement now

RICHARD M. BISSELL, JR. Project Director

RMB:djm

1-

2-RMB Chrono 25X1A 3- Approved For Release 2003/01/24 : CIA-RDP62B00844R000200260138-3

Project Chrono - 6-Project Subject 7-Project Reading